

# Motor Controllers Dynamic Braking Types RTC 40 HD12-./RTO 12..

CARLO GAVAZZI



- Control and output modules for dynamic braking of 3-phase induction motors
- Rated operational current: 18.5, 30 and 60 A DC
- Rated operational voltage: Up to 400 VACrms
- Control voltage: 10 to 32 VDC
- LED indication for line ON and brake ON

## Product Description

Dynamic braking is achieved by introducing a DC current, rectified from the mains, through the motor windings. The control module RTC 40 HD-12- is used in combination with the output module RTO 12.. to achieve dynamic braking of 3-phase induction motors with braking current up to 60 A. The desired braking time and the required brake current can be adjusted

with the TIME and BRAKE CURRENT potentiometers. The control module, which is separately supplied from an external DC voltage source, has LED indications for LINE ON and BRAKE ON. The output signal from the control module is off 350 ms before the brake current is introduced. This signal can be used to take away the AC supply of the motor.

## Ordering Key

RTC 40 HD 12 - 5

Solid State Relay  
Dynamic braking  
Control module  
Output module  
Rated operational voltage  
Rated operational current  
Control voltage  
Non-rep. peak voltage  
Rated op. frequency

RTO 1210

## Type Selection

Type	Rated operational voltage	Control voltage	Non-rep. peak voltage	Rated operational frequency
C: Control module	40: 120/208 VACrms 230/400 VACrms	HD: 10 to 32 VDC	12: 1200 V <sub>p</sub>	5: 50 Hz ± 3 Hz 6: 60 Hz ± 3 Hz
Type	Non-rep. peak voltage	Rated operational current		
O: Output module	12: 1200 V <sub>p</sub>	10: 2 x 18.5 A DC 25: 2 x 30 A DC 50: 2 x 60 A DC		

## Selection Guide

Control module	Rated operational frequency		
	50 Hz	60 Hz	
230/400 VACrms	RTC 40 HD-12-5	RTC 40 HD-12-6	
Non-rep. voltage	Rated operational current		
	18.5 A	30 A	60 A
1200 V <sub>p</sub>	RTO 1210	RTO 1225	RTO 1250

## General Specifications Control Module

	RTC 40 HD12-5	RTC 40 HD12-6
Operational voltage range Line to line	190 to 440 VACrms	190 to 440 VACrms
Non-rep. peak voltage	$\geq 1200 V_p$	$\geq 1200 V_p$
Operational frequency range	47 to 52 Hz	57 to 63 Hz
Supply current @ RUN, no output @ BRAKE, no output	$\leq 30 \text{ mA @ 32 VDC}$ $\leq 110 \text{ mA @ 32 VDC}$	$\leq 30 \text{ mA @ 32 VDC}$ $\leq 110 \text{ mA @ 32 VDC}$
Approval	CSA	CSA
CE-marking	Yes	Yes

## Control Input Specifications

Control voltage range	10 to 32 VDC
Motor running	$\geq 8 \text{ VDC}$
Motor stopped	$\leq 2 \text{ VDC}$
Adjust. braking current	Dependent on motor size
Adjust. braking time	1 to 40 s
Min. delay, stop to run	$\geq 1 \text{ cycle}$
Remanence delay	$\geq 350 \text{ ms}$

## Thermal Specifications Control Mod.

Operating temperature	-20° to +80°C (-4° to +176°F)
Storage temperature	-40° to +100°C (-40° to +212°F)

## Control Output Specifications

Minimum output voltage	Power supply less 3.5 VDC
Output current short-circuit protected	150 mA DC

## Insulation Control Module

Rated insulation voltage Input to trigger outputs	$\geq 4000 \text{ VACrms}$
--	----------------------------

## Mode of Operation

The control module RTC 40 HD12-5 (50 Hz)/RTC 40 HD12-6 (60 Hz) is used with output module RTO 12.. to achieve dynamic braking of 3-phase induction motors.

Dynamic braking is achieved by passing direct current, rectified from the mains, through the motor windings. The DC-current will then produce a static field through the short-circuited rotor, and the induced rotor current will create a torque opposite to the direction of rotation.

### Note:

This means that no braking takes place when the motor revolution is zero. The desired braking time can be set by means of the BRAKE TIME potentiometer. The

braking current can be adjusted by means of the BRAKE CURRENT potentiometer to achieve motor stop within the desired time.

### Note:

Avoid excessive braking current after the motor has been stopped, as this will create unnecessary heating of the motor.

Since the RTC/RTO configuration is only capable of braking the motor, a starting device is needed. Either a Solid State Relay, e.g. Carlo Gavazzi RZ, or a motor controller RSC 40 HD12-./RSO 12.. can be connected to the application.

To ensure safe operation the starting device must be con-

trolled by the RTC output. When the control voltage (terminal C2) is removed, braking will take place.


The control module has LED indication for line ON and brake ON. The control module also features remanence delay. To avoid torque shock, a delay of min. 350 ms passes from the moment the motor contactor has been released until DC voltage is reapplied to the motor windings.

To measure the braking current, always use a true rms ammeter with DC range.


In order to define the size of the output module, it is necessary to find the resistance between the two termi-

nals from the motor where the brake module will be connected. This resistance is a combination of the resistances of the motor windings and is dependent on how the motor is connected. In star connection it is a series connection of two windings (see top of next page). In delta connection it consists of two windings connected in parallel to the third winding (see top of next page).

## Mode of Operation (cont.)



Star



Delta

If the brake current is adjusted to max., full half waves are introduced to the motor, and

the DC voltage is calculated as follows:

$$U_{DC} = \frac{U_{max}}{\pi} = \frac{U_n \times \sqrt{2}}{3.14} = U_n \times 0.45$$

The max. current can be calculated as follows:

$$I_{max} = \frac{U_n \times 0.45}{\Sigma R}$$

where  $\Sigma R$  is a combination of the windings mentioned above.

Example: The resistance of the motor winding is 5  $\Omega$ .

The rated operational voltage is 400 VAC.

What is the max. current in star connection and in delta connection?

$\Sigma R$  star is  $R1 + R2 = 5 + 5 \Omega = 10 \Omega$

$\Sigma R$  delta is  $R1$  parallel to  $R2 + R3 = 3.3 \Omega$ .

The current is:

$$\frac{400 \times 0.45}{10} = 18 \text{ A}$$

for the star connection, and

$$\frac{400 \times 0.45}{3.33} = 54 \text{ A}$$

for the delta connection.

The output module has to be selected accordingly (next higher power rating).

## General Specifications Output Module

	RTO 1210	RTO 1225	RTO 1250
Operational voltage range Line to line	220 to 420 VACrms	220 to 420 VACrms	220 to 420 VACrms
Rated operational current	18.5 ADC	30 ADC	60 ADC
Approval	CSA	CSA	CSA
CE-marking	Yes	Yes	Yes

## Output Specifications Output Module

	RTO 1210	RTO 1225	RTO 1250
Non-rep. peak voltage	$\geq 1200 V_p$	$\geq 1200 V_p$	$\geq 1200 V_p$
Off-state leakage current	$\leq 10 \text{ mA}$	$\leq 10 \text{ mA}$	$\leq 10 \text{ mA}$
On-state voltage drop	$\leq 1.6 V_{rms}$	$\leq 1.6 V_{rms}$	$\leq 1.6 V_{rms}$
$I^2t$ for fusing $t=1-10 \text{ ms}$	$\leq 130 A^2s$	$\leq 450 A^2s$	$\leq 1680 A^2s$
Critical $di/dt$	$\geq 50 A/\mu s$	$\geq 50 A/\mu s$	$\geq 50 A/\mu s$
Non-rep. surge current $t=10 \text{ ms}$	160 $A_p$	300 $A_p$	580 $A_p$

## Thermal Specifications Output Module


	RTO 1210	RTO 1225	RTO 1250
Operating temperature	-20° to +70°C (-4° to +158°F)	-20° to +70°C (-4° to +158°F)	-20° to +70°C (-4° to +158°F)
Storage temperature	-40° to +100°C (-40° to +212°F)	-40° to +100°C (-40° to +212°F)	-40° to +100°C (-40° to +212°F)
$R_{th}$ junction to case	$\leq 1.4 \text{ K/W}$	$\leq 1.0 \text{ K/W}$	$\leq 0.5 \text{ K/W}$

## Insulation Output Module


Rated insulation voltage Output to case	$\geq 4000 \text{ VACrms}$
--	----------------------------



Operation Diagram




Wiring Diagram



Accessories

- Heatsinks
  - Varistors
  - Fuses
  - Temperature limit switch
  - Power supply
- For further information refer to "General Accessories".

Functional Diagram




Housing Specifications

Weight	Approx. 275 g
Housing material	Noryl, glass-reinforced
Colour	Black
Base plate	Aluminium, nickel-plated
Potting compound	Polyurethane, black
Relay	
Mounting screws	M5
Mounting torque	$\leq 1.5$ Nm
Control terminal	
Mounting screws	M3
Mounting torque	$\leq 0.5$ Nm
Power terminal	
Mounting screws	M5
Mounting torque	$\leq 1.5$ Nm


## Dimensions

### RTO 12..



All dimensions in mm


### RTC 40 HD12-.



## Applications


### Measuring point for DC load current

Note: When using a clamp-meter, be sure that it is capable of measuring DC-current.



### Brake current

Typical behaviour of braking torque as a function of motor speed: As will be seen from the curve, the braking torque will be relatively low at nominal motor speed. As the revolution speed decreases, the braking torque increases until the speed approaches zero. Then, the braking torque decreases. With zero speed the braking torque is at zero.



### Protection of the motor

A possible way of protecting the motor against overheating where dynamic braking is used is to mount a temperature sensor, PTC or Klaxon, between the motor windings.

Thermal relays will normally be sensitive to the current asymmetry occurring while braking. The thermal relay may trip undesirably.

### Connection to the mains

As this type of brake relay has a semiconductor between two phases, it is always recommended to protect it against high surge currents as well as possible voltage transients.


The protection consists of two elements:

1. A semiconductor fuse rated below the max. load integral ( $I^2t$ ) for the output module.
2. A voltage-dependent resistor (MOV) to prevent voltages higher than the blocking voltage of the output modules. Without MOV, voltage transients might trigger the output module and subsequently cause undesirable fuse blowing.

### Connection to 3-phase SSR

F1 - F3: Ultrafast fuses with  $I^2t$  rated lower than the  $I^2t$  value of the output module.  
P1 - P5: Varistors for 420 V mains with a diameter of 20 mm.

## Applications (cont.)



### Connection to a 3-phase mechanical relay

Special precautions should be taken where the driving element is a mechanical contactor. The electrical voltage peaks from the contactor must be dampened by the use of RC snubbers.

Varistor: S20 K 420 Siemens  
RC: PMR 209 Rifa 47Ω/0.1 μF  
d1: Feme MZP  
Fuse: See "General Accessories".

The output of the braking module is disconnected from the motor terminals when the motor is running and is connected only when the motor is in brake or stop mode. This feature together with a mechanical and electrical interlock (dotted line) between motor and brake relay will help to reduce the risk of malfunction.

S1 closed: The motor is running.

S1 opens: The adjusted current brakes the motor within the adjusted time.


If S1 is closed before the end of a braking cycle, the relays will return to RUN mode within 0.1 s.

### Connection to two 1-phase SSRs

Note: Motor protecting relay is not shown.

F1 - F3: Ultrafast fuses with I<sup>2</sup>t rated lower than the I<sup>2</sup>t value of the output.

P1 - P4: Varistors for 420 V mains with a diameter of 20 mm.




\* SSR 3: If switching of all three phases is desired.

SSR 1, SSR 2: Carlo Gavazzi type RA 48 xx-D 12 (1200 V blocking voltage).

S1 closed: The motor is running.

S1 opens: The adjusted current brakes the motor within the adjusted time.

If S1 is closed before the end of a braking cycle, the relays will return to RUN mode within 0.1 s.



F1 - F3: Ultrafast fuses with I<sup>2</sup>t rated lower than the I<sup>2</sup>t value of the output module. F3 is optional since there is no semiconductor in L3.

P1 - P3: Varistors for 420 V mains with a diameter of 20 mm.

When S1 is closed, the motor is running.

When S1 is opened, the motor brakes and stops.


Note: The max. allowable delay time for switching off is 350 ms. Do not use more than one auxiliary relay.

The d1 relay could also be a Solid State Relay, e.g. Carlo Gavazzi relay type RP1A23D3.

## Applications (cont.)


When using Solid State Relays, a resistor of 1 k $\Omega$  should be connected between output (O) and negative (-) on the RTC control unit to ensure

that the output voltage from the RTC control unit is lower than the drop-out voltage for the Solid State Relay.




### Start - stop function

Start-stop function  
(only control circuit is shown)




*With auxiliary diode*



*With auxiliary relay*


### Interconnection of braking and reversing SSRs



F1 - F5: Ultrafast fuses with I<sup>2</sup>t rated lower than the I<sup>2</sup>t value of the relevant output modules.

P1 - P6: Varistors for 420 V mains with a diameter of 20 mm.

## Interconnection of soft starting and braking SSRs



F1 - F5: Ultrafast fuses with I<sub>2t</sub> rated lower than the I<sub>2t</sub> value of the relevant output modules.

P1 - P5: Varistors for 420 V mains with a diameter of 20 mm.

## Thermal considerations

## Motor

Dynamic braking of 3-phase induction motors creates power dissipation in the motor. The DC current dissipates power in the stator windings, and the stored energy in the rotating machine is dissipated in the rotor during braking. Consequently, the best way of protecting the motor will be to install temperature sensors in the motor windings.

## Solid State Relay

Due to the relatively high power dissipation in the motor the RUN and BRAKE mode ratio is normally less than 0.1.

$$\frac{\text{Brake time}}{\text{Run + Brake time}} < 0.1$$

This gives negligible power dissipation in the braking Solid State Relay. Under normal conditions it will be sufficient to mount the relay on to the chassis. If no metal backplate is available, a heatsink must be used:

RTO 1210  $R_{th} = 2.5 \text{ K/W}$

RTO 1225  $R_{th} = 2.5 \text{ K/W}$

RTO 1250  $R_{th} = 1 \text{ K/W}$

The heatsinks are sufficient for ambient temperatures up to 60°C (140°F).